

## Inspection report – 2026 Case 1107 NX-D

Serial No: NKJ1107NETKT10858 | Hours: 4 | Location: Dubai, United Arab Emirates | SKU: 858

---

### Key Features & Condition

Safety Certification Label	N/A
Equipment Parts Manual	N/A
Horn Function	Yes
Travel Alarm	Yes
Operator's Manual	Yes
Emission Compliance Label	N/A
Emergency Switch	Yes
EPA	N/A
Closed cabin	N/A
Control Protection	Yes
Tools	N/A
Aircondition / Heater	N/A
Water Spray System	N/A

### Operator Cabin Details

Seat and Arm Support	Ok
Control Levers, Control Switches	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Windows& mirrors	No window, 2 mirrors
Wiper, washer	N/A
Electrical System	Ok
Cabin Structure	Ok
Floor cover mat	N/A

### Engine & Performance

Fuel Injection System Type	Electronic
Engine Model Details	H4C510122
Fluid Leaks	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Oil Check	Ok
Exhaust System and Muffler	Ok
Exhaust Smoke	Normal
Engine Cooling System	Ok
Engine Blow-by Check	Normal
Belts and Air/Oil Filters	Ok
Coolant	Ok

---

## Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Stairs, Handrails	Ok
Paintwork	Ok
Water tanks	N/A
Drum Condition	Ok
Rubber Drum Isolators	Ok
Drum Scraper	Ok
Lights	Ok, 1- light protection has little dent.
Batteries	Ok

---

## Hydraulic System

Hoses & Lines	Ok
Drum Vibration Motors	Ok
Pumps & Valves	Ok
Steering Cylinders	Ok
Hydraulic Tank	Ok

---

## Limited Functional Testing & Operation

Steering	Ok
Transmission Test	Ok
Dash Console	Ok
Brake/Park Brake	Ok
Water Spray System	N/A
Drive Motors Front	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Drive Motors Rear	Ok
Drum Vibration	Ok

---

## Tires Condition (%)

Right	100%, CEAT, 23.1-26R3, New, Tubeless
Left	100%, CEAT, 23.1-26R3, New, Tubeless

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

