

Inspection report – 2012 Doosan DX340LC

Hours: 11470.0 | Location: Dubai, United Arab Emirates | SKU: 1320552

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple And Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System Addblue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

Operator Cabin Details

Seat And Arm Support	Ok
Cab Doors & Covers	Ok, door lock need repair
Control Levers, Control Stick	Ok, right control stick is broken
Windows And Mirrors	Ok, no mirrors
Dashboard Screen, Gauges	Functional, monitor controls not functional and monitor base is missing
Warning Alarms Message	Ok
Washer, Wipers	N/A
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok
Note	Diesel tank cover is missing

Engine & Performance

Fuel Injection System	Electronic
-----------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Engine Model	Doosan DL08
Engine Cooling System	Ok
Engine Oil Check	Ok
Cooling System	Ok
Coolant	Normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok, the battery box is dented.
Steps And Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Ok, 1 light need change
Battery Check	Need change
Cabin Compartments	Ok
Exterior Paint Condition	Ok, some parts repainted

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
---------------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Excavator Self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, minor loose
Slewing Ring Bearing Movement Check	Ok
Swing Drive And Brake Test	Ok
Drive Force Test	Ok

Attachments

Attachments Model	bucket
Size	W1080, H1200, D1000 mm
Status	Ok, 4 teeth are missing
Coupler Status	Ok
Second Attachments Model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	60%
Track Shoes	50%
Idlers	60%
Shoe Width In Mm:	600
Track Pitch In Mm:	85
Carrier Rollers	30%
Track Rollers	40%
Track Links	60%
Sprocket Segments	70%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com

