

Rapport d'inspection – 2002 Caterpillar 345B

Numéro de série: CAT0345BPAMN00337 | Heure: 32388 | Lieu: United Arab Emirates | SKU: 720

Key Features & Condition

Safety Certification Label N/A Boom Hydraulic Check Valve N/A Adjustable Boom System N/A **Automatic Lubrication System** N/A Arm Hydraulic Check Valve N/A Diesel Particulate Filter N/A Hydraulic Hammer Lines Yes N/A Grapple and Shear Hydraulic Lines Diesel Exhaust Fluid System AddBlue N/A Stabilizer Blade Condition N/A N/A Horn

Operator Cabin Details

Seat and Arm Support Ok
Cab Doors & covers Ok
Control Levers, Control Stick Ok

Windows and Mirrors Ok, door window is broken, right mirror is

broken

Dashboard Screen, Gauges Functional

Warning alarms message Water sensor alarm

Washer, Wipers

Air Conditioning & Heating System

Not cooling

Cab Floor Covering N\A
Cab Structure, Gard Ok

Electrical System Need minor maintenance

Engine & Performance

Fuel Injection System Electronic Engine Model CAT 3176

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Engine Cooling System Ok
Engine Oil Check Ok
Cooling System Ok

Coolant Ok, normal water

Exhaust System & Muffler Ok
Belts & Air/Oil Filters Ok
Smoke Check

Smoke Check Normal Blowby Normal

Leaks & Seals Ok, minor leak

Exterior Condition & Visual Inspection

Main Frame & Track Frame Ok, right boom jack base is welded

Protective Covers & Sheets 5 Covers are missing Engine Hood Ok, hood is broken

Side Access Doors Minor dents, need lock repair

Steps and Handrails Ok
Boom Condition Ok
Bumpers & Catwalk Condition Ok

Arm Condition Welded

Lights Not Functional

Battery Check Ok
Cabin Compartments Ok

Exterior Paint Condition Ok,repainted

Hydraulic System

Hydraulic Leaks

Boom Hydraulic Jack

Hydraulic Pump & Valve Block

Bucket Hydraulic Jack

Functional

Functional

Functional

Functional

Performance analysis

Boom Pins Condition Ok

Excavator self- Drift Test Functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com





Arm Pins Condition Minor loose

Hydraulic Pump Noise Check Ok

Bucket Pins Condition Ok, Minor loose

Slewing Ring Bearing Movement Check Functional

Swing Drive and Brake Test Functional, need service (has greas instead of

oil)

Drive force Test Functional

Attachments

Attachments model Bucket

Size W1400, H14000, D1000 mm

Status Cracked, Welded

Coupler status Ok
Second Attachments model N/A
Size N/A
Status N/A

Undercarriage

bushings 50%
Track shoes 60%
idlers 60%

shoe width in mm: 745mm

track pitch in mm: 165mm

carrier rollers 40%
Track rollers 40%

Track links 60%, 1 broken

Sprocket segments 60%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.



Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com

