

Rapport d'inspection – 2004 Caterpillar M318

Numéro de série: CAT0M318E8AL03273 | Heure: 20329 | Lieu: Dubai, Émirats arabes unis | SKU: 795

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	Yes
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Back camera	N/A
Quick Coupler	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	Yes
Stabilizer Blade Condition	N/A
Horn	N/A
Schild Plate	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Functional
Windows and Mirrors	Ok
Dashboard Screen, Gauges	N/A
Warning alarms message	N/A
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Gard	Ok, no gard
Electrical System	Need Minor service

Engine & Performance

Fuel Injection Type	Mechanical
---------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Model	3116T
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, air filter pipe is broken
Smoke	Normal
Coolant	Ok, normal water
Leaks& seals	Minor

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Welded
Lights	functional
Battery Check	Need change
Counterweight	Ok
Exterior Paint Condition	Ok,fully repainted blue

Hydraulic System

Hydraulic Leaks	Minor
Boom Hydraulic Jack	Functional
Hydraulic Pump & Valve Block	Functional, weak
Mono Boom Jack	Not functional
Bucket Hydraulic Jack	Functional
Arm Hydraulic Jack	Functional
Pump Noises Check	Normal
Bucket Swing cylinder	N/A
Schild Blade Jack	Functional



Transmission & drive train

Transmission Gear	Functional
Axles	Ok
Swivel Joint	Ok
Universal Joint	Ok

Limited Functional Testing & Operation

Boom Pins Condition	Ok, minor loose
Excavator self- Drift Test	Weak
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Normal
Brack & Parking Brack	weak
Suspension Lock	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Functional
Swing Drive and Brake Test	Weak
Drive force Test	Weak
Slewing Ring Lock	Ok

Attachments

Attachments model	Bucket
Size	W930, H1000, D700 mm
Status	Ok
Coupler status	Ok
Second Attachments model	Schild blade
Size	W2750, H550 mm
Status	Ok

Tires Estimated Remaining Life %

Front Right	30%
Front Left	20%
Rear Right	20%
Rear Left	20%
Size	10.00R20

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Type	Tube (on road)
Spacer Rings	N/A
Damages / Cuts	Minor
Nuts	7 nuts are missing

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

