

PLANT & EQUIPMENT

Rapport d'inspection – 2006 Kobelco CKE1350

Numéro de série: GN0302049 | Heure: 33294 | Lieu: Dubai, Émirats arabes unis | SKU: 1187

Key Features & Condition

CE Labeling	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	Yes, external
Extended Fuel tank	N/A
Horn	N/A
Hook speed sensor	Yes, not assembled
Boom angle sensor	Yes
Radiuous sensor	Yes
Hook weight sensor	Yes
Load sensor	Yes
Hook	Yes

Truck Cab

Driver Seat	Ok, need upholstery
Switches, Levers	Ok
Gauges, Warn Lights	Ok
Aircon / Heater	External, not cooling
Cab Doors	Ok
Windows, Mirrors	Ok, no mirrors
Wipers, Washers	Ok, only front
Interior, Covers	Ok

Engine

Injection Type	Electronic
Engine Model	Mitsubishi 6D24-TLU2H
Leaks, Seals	Ok, minor from injector cover
Oil Condition	Ok
Exhaust/Muffler	Ok



PLANT & EQUIPMENT

Cooling System	Ok
Smoke, Fume	Ok, minor
Blow By	Normal
Belts, Pulleys	Ok, ac belt missing
Coolant Condition	Normal water

Visual inspection exterior

Chassis, Frames	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok
Boom Condition	Ok, not assembled
Cooler Grill	Ok
Bumpers	Ok, self assemble type
Lights	Ok, only 2, 1 need bulb
Batteries	Ok
Main Hook	Available, not assembled
Auxiliary Hook	Available, not assembled
machine punched number	Ok

Hydraulics

Hydraulic Leaks	Ok
Hydraulic Pump / Valve	Ok
hydraulic stabilizer	Ok

Crane Condition / Limited Test

Drive Forward & Back	Ok
Controls, Levers	Ok
Boom Conditions	Available, not assembled
Telescopic Segments	N/A
Hydraulic Cylinders	Ok, only outriggers
Swing Bearing / Drive	Ok
Hose Lines	Ok
Lift Limitations	Not assembled

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Main Hook	Not assembled
Auxiliary Hook	Not assembled
Outriggers	Ok
Boom Pins Condition	Ok
Hydraulic Pump Noise Check	Ok

Undercarriage

Bushings Pin	60%
Track shoes	60%
Idlers	60%
Carrier rollers	2 pic 40%, 2 pic need change
Track rollers	50%
Track links pine	40%, minor loose
Sprocket segments	70%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

