

Rapport d'inspection – 2007 Caterpillar 345C

Numéro de série: CAT0345CKPJW01768 | Heure: 21494 | Lieu: Dubai, Émirats arabes unis | SKU: 721

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

Operator Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, mirrors are missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Engine Ecm error, water separator warning
Washer, Wipers	N/A
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Guard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection System	Electronic
Engine Model	C13 Acert

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Minor leak

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Welded
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Not Functional
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, repainted

Hydraulic System

Hydraulic Leaks	Minor oil leaks
Boom Hydraulic Jack	Minor oil leaks
Hydraulic Pump & Valve Block	Functional
Bucket Hydraulic Jack	Functional
Arm Hydraulic Jack	Functional

Performance analysis

Boom Pins Condition	Ok, minor loose
Excavator self- Drift Test	Functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Minor loose
Slewing Ring Bearing Movement Check	Functional
Swing Drive and Brake Test	Functional
Drive force Test	Functional

Attachments

Attachments model	Bucket
Size	W1300, H1350, D1150 mm
Status	Cracked, Welded
Coupler status	Cracked
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

bushings	60%
Track shoes	70%, 1 broken
idlers	70%
shoe width in mm:	770mm
track pitch in mm:	85mm
carrier rollers	70%
Track rollers	60%
Track links	70%
Sprocket segments	70%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

