

PLANT & EQUIPMENT

Rapport d'inspection – 2014 Komatsu GD705-5

Numéro de série: KMTGD031JEA026087 | Lieu: Dubai, Émirats arabes unis | SKU: 1156

Key Features & Condition

Safety Certification Label	N/A
Supplemental Steering System	N/A
Ground Loosening Tool (Scarifier)	N/A
Emission Compliance Label	N/A
Snowplow Attachment	N/A
Equipment Parts Manual	N/A
Ripper Control Valve	Yes
All-Wheel Drive System	Yes
Ground Tearing Tool (Ripper)	Yes
Operator's Manual	N/A
Front Plow Blade	N/A

Operator Cabin Details

Seat	Ok
control levers	Ok
Dashboard Gauges & Lights	Ok, dashboard cover broken,
Warning alarms Lights, Message	E01,CA428 Engine
Air conditioning	Not cooling
Cab Floor Covering	Ok
Windows and Mirrors	Ok
Cab Doors	Ok
Windshield Wipers and Washer	Not functional
Access Steps and Handles	Ok, one step on the driver door is broken
Cab Structure, Guard	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model Details	KOMATSU SAA6D114E-3



PLANT & EQUIPMENT

Fluid Leaks and Seals	Minor gasket leak, oil sump, engine front side, 1 injector diesel leak
Engine Oil Check	Ok, need change
Exhaust System and Muffler	Ok
Exhaust Smoke	Normal
Engine Cooling System	Ok
Engine Blow-by Check	Normal
Belts and Air/Oil Filters	Ok
Coolant Check	Ok, normal water

Exterior Condition & Visual Inspection

Main Frame Structure	Ok
Cabin Body Condition	Ok
Y-Frame Structure	Ok
Y-Frame Pivot Joint	Ok
Circle Frame & Brackets	Ok
Circle Support Brackets	Ok
Circle Gear	Ok
Blade Slide Wear Strips	Ok
Steering Linkage	Ok
Underbody Protection Plates	Ok
Exterior Paint Condition	Ok
Lights	-
Engine Access Doors	Ok
Sheet Metal	Ok
Tandem Axles	Ok
Blade Tilt Frame (saddle)	Ok
Circle Wear Strips	Ok
Circle Gear Box	Ok
Articulating Centre Pins Wear	Ok
Front Axle Oscillating Pin Wear	Ok
Wheel Tilt Linkage	Ok
Main Blade	Ok
Ground Ripper	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Batteries

Need replace

Frame Stamp Serial Number

Ok

Hydraulic System

Hydraulic Leaks

Pump minor leak

Rotating Gear Drive

Ok

Hydraulic Control Valves

Ok, minor leak and sound

Hydraulic Pumps

Ok

Saddle Positioning Cylinder

Ok

Steering Hydraulic Cylinders

Ok

Blade Cylinders/ Angle, lift, side

Ok

Ripper Hydraulic Cylinders

Ok

Articulation Hydraulic Cylinders

Ok

Tires lean cylinder

Ok

Limited Functional Testing & Operation

Gear Shifting Test

Functional

Tandem Axle Noise Check

Ok

Brake System Test

Need minor service

Steering Function Test

Functional

Tires Lean Function Test

Functional

Electrical System Check

Need minor service

Blade Attachment Pins

Functional

Blade Side Movement Shifting

Functional

Rotating Circle Movement Check

Functional

Front Blade Function Test

Functional

Ripper & Scarifier Function Test

Functional

Steering Tires Angle Adjustment

Functional

Clutch Operation Test

Functional

Tires Inspection

Front Right Tire

30%

Front Left Tire

30%

Center Right Tire

40%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Center Left Tire	Damaged, need change
Rear Right Tire	30%
Rear Left Tire	70%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

