

PLANT & EQUIPMENT

Rapport d'inspection – 2015 New Holland B90B

Numéro de série: FNH0B90BNFHH01405 | Heure: 19528 | Lieu: Dubai, Émirats arabes unis | SKU: 1169

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	Not functional
Auxiliary Lines	N/A
4WED	Yes
Extended Stick	N/A
Rear Quick Coupler	Yes
All Wheel Steer	Yes
Fork	N/A
Emission Compliance Label	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Ok, left door lock need service
Controls, Levers	Ok, outriggers levers hard move
Windows and Mirrors	front window cracked, the door glass is changed to plastic, and there is UV degradation
Dashboard Screen, Gauges	Ok
Warning alarms message	N/A
Washer, Wipers	Not functional
Air Condition & Heating System	Not functional
Cab Floor Covering	Ok, minor cut
Cab Structure	Ok, 1 interior cover broken
Electrical System	Need service

Engine & Performance



PLANT & EQUIPMENT

Fuel Injection Type	Mechanical
Engine Model	4.5 litre FPT Industrial engine
Engine Cooling System	Ok, minor leak from reservoir tank
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Ok minor welding, minor hole
Belts & Air/Oil Filters	Need change
Smoke	Normal
Coolant	Ok
Fluid Leaks	Gasket leak, rear cover leak, oil sump leak
fuel pump & diesel system	Functional

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Sheet Metal	Ok, minor bend
Wheel Fenders	Ok
Lights Check	Need 4 bulbs
Battery Check	Need change, alternator service
Boom	Ok
Stick	Ok
Stick Extension	N/A
Rims, Wheel Nuts	Ok
Loader Frame & Hinges	Ok

Power Train Inspection

Axles and Differentials	Ok, minor leak from differentials
Transmission Leak	Minor leak from drive shaft
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok, minor loose
Transfer Gear Type	Manual with semi auto control

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Hydraulic System

Hydraulic Leaks	Ok, minor
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	minor leak from control valve
Swing Cylinders	Minor leak
Boom Cylinder	Minor leak
Stick Cylinder	Ok
Bucket Cylinder	Ok
Clamshell Cylinder	N/A

Limited Functional Testing & Operation

Steering Function Test	Functional
Transmission Operation Test	Functional
Loader Stall Test	Functional
Braking System Test	Functional, need service
Pins Boom	Minor loose
Pins Stick / Extension	Minor loose
Rear Bucket Linkage	Functional
Loader Pins & Hinges	Functional
Outriggers & Pads	Functional
Boom Side Tilt	N/A

Attachments Estimated Remaining Life %

Front Bucket	-
Size	W2200, H970, D600 mm
Condition	Ok
Rear Bucket	-
Size	W570, H700, D450 mm
Condition	Ok
Attachment Coupler	Ok

Tires Estimated Remaining Life %

Front Right	-
-------------	---

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Tire Brand & Size Details	OZKA 12.5/80-18
Tire Remaining Life Percentage	70%
Tire Condition Notes	Ok
Front Left	-
Tire Brand & Size Details	OZKA 12.5/80-18
Tire Remaining Life Percentage	20%
Tire Condition Notes	Big side cut
Rear Right	-
Tire Brand & Size Details	FARMBOY 16.9-28
Tire Remaining Life Percentage	70%
Tire Condition Notes	Ok
Rear Left	-
Tire Brand & Size Details	Marris 16.9-28
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok, dry

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

