

PLANT & EQUIPMENT

Rapport d'inspection – 2015 TATA Daewoo K6DVF

Numéro de série: KL3K6DVF1FK000626 | Lieu: Dubai, Émirats arabes unis | SKU: 1108

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Manual Shift	Yes
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	N/A
Horn off-on	Not functional
Tachograph	N/A
Auto Lube	N/A
A/C	Not functional
Navigation	N/A
ABS	Ok
Driver bed	Ok
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	N/A
Turbo-Retarder-Clutch	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	N/A
truck type	6x4 DUMP

Truck Cabin Details

Seat and Arm Support	Ok, need upholstery
----------------------	---------------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Cab Doors & covers	Ok, lock need repair
Controls, Levers	Functional
Windows and Mirrors	Ok, front glass broken
Dashboard Screen, Gauges	need service, only collant tempreature works
Warning alarms message	N/A , Dashboard need service
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Minor cut
Interior, Covers	Need service
Passenger Seat	Ok
Radio	N/A

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	Doosan Infracore DE12Ti
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Belt & Air filter need replace
Smoke	Normal
Coolant	Normal water
Fluid Leaks	Ok
Starting	Functional, hard start

Exterior Condition & Visual Inspection

Chassis, Frames	Ok
Frame Stamp Serial Number	Not Found
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok
Lights / Batteries	Need new bulb, change batteries

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Fenders	Ok
Suspension Springs/Hangers	Ok, leaf spring center bolt minor loose
Suspension Bushings	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Ok
Clutch	Ok

Truck Limited Functional Test

Transmission Forward	Functional
Transmission Reverse	Functional
Steering	Functional
Automatic Group Select	N/A
Service Brake	Functional
Park Brake	Functional
Electrics	Need minor service
Retarder	Not tested

Hydraulics

PTO Pump	Not functional
hydraulic cylinder	Not functional
cabine lift cylinder & valve	Ok

Tires

Axle 1 / RHS (%) / LHS (%)	RHS 40 (%) / LHS 70 (%)
Axle 2 Inside / RHS (%) / LHS (%)	RHS 60 (%) / LHS 70 (%)
Axle 2 Outside / RHS (%) / LHS (%)	RHS 60 (%) / LHS 70 (%)

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 3 Inside / RHS (%) / LHS (%)

RHS 70 (%) / LHS 70 (%)

Axle 3 Outside / RHS (%) / LHS (%)

RHS 70 (%) / LHS 70 (%)

Tire Size

12 R 22.5 tubless

Cargo box

size

L 5400 , W 27500 , H 1400 mm

condition

Ok, minor dents

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

