

# PLANT & EQUIPMENT

## Rapport d'inspection – 2015 TOYOTA HILUX

Numéro de série: MR0FX22G8F1437986 | Km: 635019 | Lieu: Dubai, Émirats arabes unis | SKU: 1124

---

### Specifications and Standards

|                       |                     |
|-----------------------|---------------------|
| 4WD                   | Yes                 |
| Draw Bar              | N/A                 |
| Spare Tire            | N/A                 |
| Spare Tire Tools      | N/A                 |
| Xenon Head Lights     | N/A                 |
| Gear Paddle Shifter   | N/A                 |
| Rear camera           | N/A                 |
| Air Condition         | Not cooling         |
| Cooling&Heating Seats | N/A                 |
| Radio                 | Yes                 |
| Car Type              | Double cabin pickup |
| hill descent control  | Yes                 |
| cruise control        | N/A                 |

---

### Interior

|                   |                             |
|-------------------|-----------------------------|
| Seats             | driver seat need upholstery |
| Switches          | Ok                          |
| Gauges            | Ok                          |
| Aircon / Heater   | Not cooling                 |
| Ceiling           | Ok                          |
| Cab Doors         | Ok                          |
| Windows           | Ok                          |
| Wipers            | Need replacment             |
| Floor Mates       | Ok                          |
| Glove Compartment | Broken                      |

---

### Engine

|       |                    |
|-------|--------------------|
| Model | 2.7L 2TR-FE Engine |
|-------|--------------------|

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT

|                    |                                             |
|--------------------|---------------------------------------------|
| Leaks              | minor leak from head gasket & steering pump |
| Oil Condition      | Ok                                          |
| Exhaust            | Ok                                          |
| Cooling System     | Ok                                          |
| Fuel Type          | Petrol                                      |
| Sound              | Ok                                          |
| Smoke              | Normal                                      |
| Blow By            | Normal                                      |
| Belts              | Ok, dry need change                         |
| Power              | Ok                                          |
| Coolant            | Ok                                          |
| Size & Horse Power | 2.7 L                                       |

---

## Exterior

|                    |                                                   |
|--------------------|---------------------------------------------------|
| Chassis            | Ok, minor rust                                    |
| Roof               | Ok                                                |
| Under Engine Cover | Ok                                                |
| Door Handles       | Ok                                                |
| Paintwork          | Ok, front and rear bumper need fix and paint      |
| Cooler Grill       | Missing                                           |
| Bumpers            | Front bumper broken                               |
| Fuel Tank Cover    | Ok                                                |
| Lights             | 2 need bulbs, rear right is broken, 3 need polish |
| Deck               | Ok                                                |

---

## Power Train

|                   |           |
|-------------------|-----------|
| Axels             | Ok        |
| Gearbox           | Ok        |
| Transmission Gear | Ok        |
| Universal Joints  | Ok        |
| Differentials     | Ok        |
| Gear Type         | Automatic |

---

## Limited Functional Test

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT

|               |                                     |
|---------------|-------------------------------------|
| Drive Forward | Ok                                  |
| Drive Reverse | Ok                                  |
| Service Brake | Ok                                  |
| Steering      | Ok, minor leak from pump            |
| Wheel Bearing | Ok                                  |
| Suspensions   | Ok, need to change bushing and arms |
| Park Brake    | Ok                                  |

---

## Tires Axle 1

|              |                 |
|--------------|-----------------|
| RHS (%) rem. | 20% need change |
| LHS (%) rem. | 20% need change |

---

## Tires Axle 2

|              |                     |
|--------------|---------------------|
| RHS (%) rem. | 40% dry need change |
| LHS (%) rem. | 40% dry need change |

---

## Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

