

Rapport d'inspection – 2016 JCB 3DX

Numéro de série: HAR3DXSUT01498971 | Heure: 2805 | Lieu: United Arab Emirates | SKU: 805

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	N/A
Auxiliary Lines	N/A
4WED	Yes
Extended Stick	N/A
Rear Quick Coupler	N/A
All Wheel Steer	N/A
Fork	N/A
Emission Compliance Label	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok, Seat turn lock need repair
Cab Doors & covers	Ok, Right door lock need service
Controls, Levers	Ok
Windows and Mirrors	Only 1 mirror
Dashboard Screen, Gauges	Ok, Speed gauge not functional
Warning alarms message	2 Warning lights not functional
Washer, Wipers	Not functional
Air Condition & Heating System	N/A
Cab Floor Covering	Ok, Minor cut
Cab Structure	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	JCB 444
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Oil need change
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Minor
Coolant	Ok, Normal water
Fluid Leaks	Ok
Fuel Pump	Functional, need minor service

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok, Some parts repainted
Sheet Metal	Ok
Wheel Fenders	Ok
Lights Check	Ok, Need 1 bulb
Battery Check	Ok
Boom	Ok
Stick	Ok, Bucket bushing welded
Stick Extension	N/A
Rims, Wheel Nuts	Ok, 4 Nuts missing
Loader Frame & Hinges	Ok, Bucket bushing welded

Power Train Inspection

Axles and Differentials	Ok
Transmission Leak	Oil filter leaks
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Manual

Hydraulic System

Hydraulic Leaks	Ok
-----------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok
Swing Cylinders	Ok
Boom Cylinder	Ok
Stick Cylinder	Ok
Bucket Cylinder	Ok
Clamshell Cylinder	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Loader Stall Test	Ok
Braking System Test	Ok, Park break need maintenance
Pins Boom	Ok, Minor loose
Pins Stick / Extension	Ok, Minor loose
Rear Bucket Linkage	Ok, Minor loose
Loader Pins & Hinges	Ok, Minor loose
Outriggers & Pads	Ok
Boom Side Tilt	Ok

Attachments Estimated Remaining Life %

Front Bucket	-
Size	W2150, H1000, D500 mm
Condition	Ok
Rear Bucket	-
Size	W770, H730, D500 mm
Condition	Ok
Attachment Coupler	Minor crack

Tires Estimated Remaining Life %

Front Right	-
Tire Brand & Size Details	MPT 12.0/75-18
Tire Remaining Life Percentage	100%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Condition Notes	Ok
Front Left	-
Tire Brand & Size Details	MPT 12.0/75-18
Tire Remaining Life Percentage	100%
Tire Condition Notes	Ok
Rear Right	-
Tire Brand & Size Details	BKT 16.9-28
Tire Remaining Life Percentage	70%
Tire Condition Notes	Some side scratch
Rear Left	-
Tire Brand & Size Details	JCB 16.9-28
Tire Remaining Life Percentage	70%
Tire Condition Notes	Some side scratch

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

