

Rapport d'inspection – 2017 Hyundai R210-7

Numéro de série: N601D02029 | Heure: 8624 | Lieu: Dubai, Émirats arabes unis | SKU: 982

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	OK/ hard visual sunburnt
Warning alarms message	Electrical alarm
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Ok
Cab Structure	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection System	Mechanical
Engine Model	6BT- 5.9 - C
Engine Cooling System	Ok, Broken coolant tank

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Minor leak from rocker gasket

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Need 3 bulbs
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok, swing drive minor leak
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Functional
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Functional
Arm Pins Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pump Noise Check	Minor
Bucket Pins Condition	Ok
Swing Ring Bearing Movement Check	Minor loose
Swing Drive and Brake Test	Functional
Drive force Test	Ok

Attachments

Attachments model	Bucket
Size	W1080mm, H1070mm, D980mm.
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	70%
Track shoes	70%
Idlers	L 70%, R 80%
Shoe width in mm:	600
Track pitch in mm:	80
Carrier rollers	70%
Track rollers	70%
Track links	70%
Sprocket segments	70%

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

