

## Rapport d'inspection – 2017 Hyundai Robex 500LC-7

Numéro de série: HHKHNB02AE0000901 | Heure: 9602 | Lieu: Dubai, Émirats arabes unis | SKU: 972

---

### Key Features & Condition

|                                     |     |
|-------------------------------------|-----|
| Safety Certification Label          | N/A |
| Boom Hydraulic Check Valve          | N/A |
| Adjustable Boom System              | N/A |
| Automatic Lubrication System        | N/A |
| Arm Hydraulic Check Valve           | N/A |
| Diesel Particulate Filter           | N/A |
| Hydraulic Hammer Lines              | N/A |
| Grapple and Shear Hydraulic Lines   | N/A |
| Diesel Exhaust Fluid System AddBlue | N/A |
| Stabilizer Blade Condition          | N/A |
| Horn                                | -   |

### Operator Cabin Details

|                                   |                     |
|-----------------------------------|---------------------|
| Seat and Arm Support              | Ok                  |
| Cab Doors & covers                | Ok                  |
| Control Levers, Control Stick     | Ok                  |
| Windows and Mirrors               | Ok, mirrors missing |
| Dashboard Screen, Gauges          | Ok                  |
| Warning alarms message            | Ok                  |
| Washer, Wipers                    | Wiper missing       |
| Air Conditioning & Heating System | Ok                  |
| Cab Floor Covering                | Ok                  |
| Cab Structure, Gard               | Ok                  |
| Electrical System                 | Ok                  |

### Engine & Performance

|                       |               |
|-----------------------|---------------|
| Fuel Injection System | Electrical    |
| Engine Model          | cummins QSM11 |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |        |
|--------------------------|--------|
| Engine Cooling System    | Ok     |
| Engine Oil Check         | Ok     |
| Cooling System           | Ok     |
| Coolant                  | Ok     |
| Exhaust System & Muffler | Ok     |
| Belts & Air/Oil Filters  | Ok     |
| Smoke Check              | Normal |
| Blowby                   | Normal |
| Leaks & Seals            | Ok     |

---

## Exterior Condition & Visual Inspection

|                             |                               |
|-----------------------------|-------------------------------|
| Main Frame & Track Frame    | Ok                            |
| Protective Covers & Sheets  | Ok                            |
| Engine Hood                 | Ok                            |
| Side Access Doors           | Ok                            |
| Steps and Handrails         | Ok                            |
| Boom Condition              | Ok                            |
| Bumpers & Catwalk Condition | Ok, Counterweight minor crack |
| Arm Condition               | Ok                            |
| Lights                      | Ok, need 3 bulbs              |
| Battery Check               | Ok                            |
| Cabin Compartments          | Ok                            |
| Exterior Paint Condition    | Ok                            |

---

## Hydraulic System

|                              |    |
|------------------------------|----|
| Hydraulic Leaks              | Ok |
| Boom Hydraulic Jack          | Ok |
| Hydraulic Pump & Valve Block | Ok |
| Bucket Hydraulic Jack        | Ok |
| Arm Hydraulic Jack           | Ok |

---

## Performance analysis

|                            |    |
|----------------------------|----|
| Boom Pins Condition        | Ok |
| Excavator self- Drift Test | Ok |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                                     |    |
|-------------------------------------|----|
| Arm Pins Condition                  | Ok |
| Hydraulic Pump Noise Check          | Ok |
| Bucket Pins Condition               | Ok |
| Slewing Ring Bearing Movement Check | Ok |
| Swing Drive and Brake Test          | Ok |
| Drive force Test                    | Ok |

---

## Attachments

|                          |                       |
|--------------------------|-----------------------|
| Attachments model        | Bucket                |
| Size                     | W580, H1450, D1150 mm |
| Status                   | Ok                    |
| Coupler status           | Minor crack           |
| Second Attachments model | N/A                   |
| Size                     | N/A                   |
| Status                   | N/A                   |

---

## Undercarriage

|                    |                          |
|--------------------|--------------------------|
| bushings           | 70%                      |
| Track shoes        | 70%                      |
| idlers             | L60%, R70%               |
| shoe width in mm:  | 600                      |
| track pitch in mm: | 80                       |
| carrier rollers    | 70%                      |
| Track rollers      | 60%                      |
| Track links        | 60%                      |
| Sprocket segments  | 80% left side minor leak |

---

## Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

---



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

