

## Rapport d'inspection – 2018 JCB 380LC

Numéro de série: PUNJD38CCJ2500802 | Heure: 17170 | Lieu: Dubai, Émirats arabes unis | SKU: 953

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	Yes
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, front down glass has crack
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok, not functional
Air Conditioning & Heating System	Extenal, ok
Cab Floor Covering	N/A
Cab Structure, Guard	Ok
Electrical System	Need service

---

### Engine & Performance

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Fuel Injection System	Electronic, need service
Engine Model	JCB DIESELMAX 672 TCAE Electronic Engine.
Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Ok,normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Ok

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok, minor welding on boom lift jack base
Protective Covers & Sheets	Ok
Engine Hood	Ok, lift support is missing
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Minor crack, minor welding on bucket pin side
Lights	Ok, boom light is missing, need 2 bulbs
Battery Check	Ok
Cabin Compartments	Ok, fuse cover is missing
Exterior Paint Condition	Ok, some parts repainted

---

## Hydraulic System

Hydraulic Leaks	Ok, minor
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

---

## Performance analysis

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Boom Pins Condition	Ok, lift cylinder pin minor loose
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, minor loose
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok, swing drive oil level is high
Drive force Test	Ok, right is little weaker

---

## Attachments

Attachments model	Bucket
Size	W1550, H1300, D115 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

---

## Undercarriage

Bushings	50%
Track Shoes	60%
Idlers	R70%, L50%
Shoe Width In Mm:	600
Track Pitch In Mm:	80
Carrier Rollers	60%
Track Rollers	60%
Track Links	60%
Sprocket Segments	70%

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

