

Rapport d'inspection – 2018 JCB 3DX SUPER

Numéro de série: HAR3DXSUT02716370 | Heure: 10727 | Lieu: Dubai, Émirats arabes unis | SKU: 729

Key Features & Condition

CE Label	N/A
EPA	N/A
A/C	N/A
Auxiliary Lines	N/A
Fork	N/A
Boom Check Valve	Yes
Stick Check Valve	Yes
Op-Manual	N/A
Parts Book	N/A
Jack Hammer Lines	N/A
Extended Stick	N/A
RCS	N/A
Rear Coupler	N/A
All Wheel Steer	N/A

Cabin

Seat, Arm Rests	Ok, No armrests
Switches, Levers	Ok
Gauges & Warn Lights	Ok
Aircon / Heater	N/A
Structure	Ok
Cab Doors	Ok
Windows & Mirrors	Ok, Left mirror are missing
Wipers, Washer	Not functional
Floor Mat	Ok, Little damaged
Interior decoration plates	Ok

Engine

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Leaks & Seals	Ok
Oil Condition, Level	Ok
Exhaust, Muffler	Ok
Smoke	Normal
Coolant Condition	Normal water
Injection	Mechanical
Cooling System	Ok
Blow By	Normal
Belts & Filters	Ok

Exterior

Chassis	Ok
Engine Hood	Ok, Small dent
Stairs, Handrails	Ok
Paintwork	Ok
Sheet Metal	Ok
Fenders	Ok
Lights, Batteries	Ok, Top lights not functional

Visual Inspection

Boom	Ok
Stick	Ok, Bucket push side minor welded
Transmission Leaks	Ok, Minor leak
Axles & Differentials	Ok
Loader Frame & Hinges	Ok
Rims, Wheel Nuts	Ok

Hydraulics

Hoses & Lines	Ok, One hose leaking
Pump And Valve Bloc	Ok
Lift & Tilt Cylinders	Ok
Swing Cylinders	Ok
Clamshell Cylinder	Ok
Boom Cylinder	Ok



Stick Cylinder	Ok
Bucket Cylinder	Ok
Steering Cylinder	Ok

Functional Test

Pins Boom	Ok
Pins Stick	Ok, Minor loose
Rear Bucket Linkage	Ok, Minor loose
Pivot Pins Excavator	Ok
Boom Side Tilt	Ok
Brake & Park Brake	Brake need maintenance, Park brake not functional
Loader Pins & Hinges	Ok
Outriggers & Pads	Ok
Boom Lock	Ok
Drive Test	Ok
Steering (All Models)	Ok

Tools

Front Bucket	W2700\H950\D500mm
Rear Bucket 1	W760\H700\D510mm
Rear Bucket 2	N/A
Rear Coupler	Ok

Tires

Front Right	-
MM (%) Remaining	50%
Size, Brand	12,5\80-18 BLACKGOLD
General Condition	Ok
Front Left	-
MM (%) Remaining	60%
Size, Brand	12,5\80-18 BLACKGOLD
General Condition	Ok
Rear Right	-

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



MM (%) Remaining	90%
Size, Brand	16,9-28 MUSCLEROK
General Condition	Ok
Rear Left	-
MM (%) Remaining	90%
Size, Brand	16,9-28 MUSCLEROK
General Condition	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

