

Rapport d'inspection – 2018 Mercedes Benz Actros 1845

Numéro de série: WDB96340310246652 | Km: 558612 | Lieu: United Arab Emirates | SKU: 764

Key Features & Condition

Safety Certification Label	Yes
Automatic Shift	Yes
Semi-Automatic	Yes
Cruise Control	Yes
Cabin Refrigerator	N/A
Add Blue	Yes
Hill Stand Aid Function	Yes
Horn Off-On	Yes
Tachograph	Yes
Auto Lube	N/A
A/C	Yes
Navigation	N/A
ABS	N/A
Driver Bed	Yes
Moving Off Aid	Yes
Lane Departure Warning System	Yes
Extended Fuel Tank	N/A
Retarder	Yes
Rear Axle Lifter	Yes
Radio	N/A
TRC	N/A
Camera Sensor	N/A
Differential Lock	Yes
Advanced Emergency Brake Assist	N/A

Truck Cabin Details

Seat And Arm Support	Ok
Cab Doors & Covers	Ok
Controls, Levers	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Windows And Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning Alarms Message	Ok, cabin lift sensor is on
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok
Interior, Covers	Ok
Passenger Seat	Ok
Radio	Not functional

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	M3B Eng. OM471, inline 6, 12.8 l, 330kW (449hp), 2200 Nm
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok, exhaust pipe elbow is welded
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, mixed water- coolant
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis, Frames	Ok
Sheet Metal, Covers	Ok, batteries cover is missing
Steps, Grab Irons	Ok, left step minor cracked
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok, side minor crack
Lights / Batteries	Ok
Fenders	Ok, front right is broken

Power Train

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok, Auto
Universal Joints	Ok
Transmission	Ok
Clutch	N/A

Truck Limited Functional Test

Transmission Forward	Ok
Transmission Reverse	Ok
Automatic Group Select	Ok
Service Brake	Ok
Park Brake	Ok, Little weak
Electrics	Ok
Retarder	Ok

Tires

Axle 1 / RHS mm (%) / LHS mm (%)	80% /80%
Axle 2 Inside / RHS mm (%) / LHS mm (%)	40% / 40%
Axle 2 Outside / RHS mm (%) / LHS mm (%)	40% / 40%
Tire Size	315 (80R22.5)

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

