

Rapport d'inspection – 2018 Mercedes Benz Actros 1845

Numéro de série: WDB96340310246651 | Lieu: United Arab Emirates | SKU: 763

Key Features & Condition

Safety Certification Label	Yes
Automatic Shift	Yes
Semi-Automatic	Yes
Cruise Control	Yes
Cabin Refrigerator	N/A
Add Blue	Yes
Hill Stand Aid Function	Yes
Horn Off-On	Yes
Tachograph	Yes
Auto Lube	N/A
A/C	Yes
Navigation	N/A
ABS	N/A
Driver Bed	Yes
Moving Off Aid	Yes
Lane Departure Warning System	Yes
Extended Fuel Tank	N/A
Retarder	Yes
Rear Axle Lifter	Yes
Radio	Yes
TRC	N/A
Camera Sensor	N/A
Differential Lock	Yes
Advanced Emergency Brake Assist	N/A

Truck Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok, The transmission's/braking common lever is faulty, A malfunction in the exhaust gas treatment system
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Interior, Covers	Ok
Passenger Seat	Ok
Radio	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	M3B Eng. OM471, inline 6, 12.8 l, 330kW (449hp), 2200 Nm
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis, Frames	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok, side minor crack
Lights / Batteries	Ok
Fenders	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok, late response (alarm message)
Universal Joints	Ok
Transmission	Ok
Clutch	N/A

Truck Limited Functional Test

Transmission Forward	Ok
Transmission Reverse	Ok
Automatic Group Select	Ok
Service Brake	Ok
Park Brake	Ok
Electrics	Ok
Retarder	Ok

Tires

Axle 1 / RHS mm (%) / LHS mm (%)	70% / 70% Out of date
Axle 2 Inside / RHS mm (%) / LHS mm (%)	30% / 40% Out of date
Axle 2 Outside / RHS mm (%) / LHS mm (%)	30% / 40% Out of date
Tire Size	315 (80R22.5)

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com

