

Rapport d'inspection – 2021 Caterpillar 323D3

Numéro de série: CAT0323DLFEY10703 | Heure: 2646 | Lieu: Dubai, Émirats arabes unis | SKU: 893

Key Features & Condition

| | |
|-------------------------------------|-----|
| Safety Certification Label | N/A |
| Boom Hydraulic Check Valve | N/A |
| Adjustable Boom System | N/A |
| Automatic Lubrication System | N/A |
| Arm Hydraulic Check Valve | N/A |
| Diesel Particulate Filter | N/A |
| Hydraulic Hammer Lines | Yes |
| Grapple and Shear Hydraulic Lines | N/A |
| Diesel Exhaust Fluid System AddBlue | N/A |
| Stabilizer Blade Condition | N/A |
| Horn | Yes |
| Rear Camera | N/A |
| E-Cataloge | N/A |
| Radio | N/A |

Operator Cabin Details

| | |
|-----------------------------------|-----------------------------|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok |
| Control Levers, Control Stick | Ok |
| Windows and Mirrors | Ok, right mirror is missing |
| Dashboard Screen, Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | N/A |
| Air Conditioning & Heating System | Ok |
| Cab Floor Covering | Ok, minor cut |
| Cab Structure, Guard | Ok |
| Electrical System | Ok |

Engine & Performance

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|--|
| Fuel Injection System | Mechanical |
| Engine Model | C7.1 1106C – 6 cylinder mechanical injection |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Coolant | Ok, normal water |
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok |
| Smoke Check | Normal |
| Blowby | Normal |
| Leaks & Seals | Ok |

Exterior Condition & Visual Inspection

| | |
|-----------------------------|-----------------|
| Main Frame & Track Frame | Ok |
| Protective Covers & Sheets | Ok |
| Engine Hood | Ok |
| Side Access Doors | Ok |
| Steps and Handrails | Ok |
| Boom Condition | Ok |
| Bumpers & Catwalk Condition | Ok |
| Arm Condition | Ok |
| Lights | Ok, need 1 bulb |
| Battery Check | Ok |
| Cabin Compartments | Ok |
| Exterior Paint Condition | Ok, repainted |

Hydraulic System

| | |
|------------------------------|------------------------|
| Hydraulic Leaks | Minor from valve block |
| Boom Hydraulic Jack | Ok |
| Hydraulic Pump & Valve Block | Ok |
| Bucket Hydraulic Jack | Ok |
| Arm Hydraulic Jack | Ok |

Performance analysis

| | |
|---------------------|----|
| Boom Pins Condition | Ok |
|---------------------|----|

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|-------------------------------------|---|
| Excavator self- Drift Test | Ok |
| Arm Pins Condition | Ok, need side washer |
| Hydraulic Pump Noise Check | Ok, little high cased by valve block minor leak |
| Bucket Pins Condition | Ok, need side washer |
| Slewing Ring Bearing Movement Check | Ok |
| Swing Drive and Brake Test | Ok, minor oil leak |
| Drive force Test | Ok |

Attachments

| | |
|--------------------------|-----------------------|
| Attachments model | Bucket |
| Size | W1330, H1100, D750 mm |
| Status | Ok |
| Coupler status | Ok |
| Second Attachments model | N/A |
| Size | N/A |
| Status | N/A |

Undercarriage

| | |
|--------------------|--------|
| Bushings | 30% |
| Track shoes | 60% |
| Idlers | 60% |
| Shoe Width in mm: | 600 mm |
| Track Pitch in mm: | 75 |
| Carrier Rollers | 40% |
| Track Rollers | 50% |
| Track Links | 60% |
| Sprocket Segments | 50% |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

