

Rapport d'inspection – 2024 Isuzu NPR

Numéro de série: JAALP34T2R7P09510 | Km: 39177 | Lieu: United Arab Emirates | SKU: 856

Specifications and Standards

Air Conditioning System	Yes
With Crane	N/A
Dump Truck Deck	Yes
Spare Tire	Yes
Fire Extinguisher	Yes
Towing Attachment	N/A
Recovery	N/A
Xenon Headlights	N/A
Seat Belt	Yes
Android secreen	Yes
Tire Tools	Yes

Interior

Seats	Ok
Switches	Ok
Gauges	Ok
Aircon / Heater	Ok
Ceiling	Ok
Cab Doors	Ok
Windows	Ok
Wipers	Ok
Floor Mates	Ok

Engine

Fuel Injection Type	Electronic
Fuel Type	Diesel
Model	4JJ1E2N
Leaks	Ok
Oil Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Exhaust	Ok
Cooling System	Ok
Sound	Normal
Blow By	Normal
Belts	Ok
Power	Ok
Coolant	Ok

Exterior

Main Frame Structure	Ok
Body Metal	Ok
Door Handle Condition	Ok
Exterior Paint Condition	Ok
Radiator Grill Condition	Ok
Bumper Condition	Ok
Light Condition	Ok
Battery Condition	Ok

Power Train

Axels	Ok
Gearbox	Ok
Transmission Gear	Ok
Transfer Gear	Ok
Universal Joints	Ok
Differentials	Ok
Brake Drums/Disk	Ok

Limited Functional Test

Drive Forward	Ok
Drive Reverse	Ok
Service Brake	Ok
Steering	Ok
Wheel Bearing	Ok
Suspensions	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Park Brake	Ok
Tipper Hyd Jack	Ok

Tires Axle 1

RHS mm (%) rem.	80%
LHS mm (%)	80%
Cuts	Ok
Recapped	N/A
Year Model	2024

Tires Axle 2

RHS mm (%) rem.	80%
LHS mm (%)	80%
Cuts	Ok
Recapped	N/A

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

