

## Rapport d'inspection – 2007 Caterpillar 345C

Numéro de série: CAT0345CKPJW01768 | Heure: 21494 | Lieu: United Arab Emirates | SKU: 721

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

### Operator Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, mirrors are missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Engine Ecm error, water separator warning
Washer, Wipers	N/A
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

### Engine & Performance

Fuel Injection System	Electronic
Engine Model	C13 Acert
Engine Cooling System	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Oil Check	Ok
Cooling System	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Minor leak

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Welded
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Not Functional
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, repainted

---

## Hydraulic System

Hydraulic Leaks	Minor oil leaks
Boom Hydraulic Jack	Minor oil leaks
Hydraulic Pump & Valve Block	Functional
Bucket Hydraulic Jack	Functional
Arm Hydraulic Jack	Functional

---

## Performance analysis

Boom Pins Condition	Ok, minor loose
Excavator self- Drift Test	Functional
Arm Pins Condition	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Minor loose
Slewing Ring Bearing Movement Check	Functional
Swing Drive and Brake Test	Functional
Drive force Test	Functional

---

## Attachments

Attachments model	Bucket
Size	W1300, H1350, D1150 mm
Status	Cracked, Welded
Coupler status	Cracked
Second Attachments model	N/A
Size	N/A
Status	N/A

---

## Undercarriage

bushings	60%
Track shoes	70%, 1 broken
idlers	70%
shoe width in mm:	770mm
track pitch in mm:	85mm
carrier rollers	70%
Track rollers	60%
Track links	70%
Sprocket segments	70%

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

