

## Rapport d'inspection – 2021 Caterpillar 323GC

Heure: 5964.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1396072

---

### Key Features & Condition

|                                     |     |
|-------------------------------------|-----|
| Safety Certification Label          | N/A |
| Boom Hydraulic Check Valve          | N/A |
| Adjustable Boom System              | N/A |
| Automatic Lubrication System        | N/A |
| Arm Hydraulic Check Valve           | N/A |
| Diesel Particulate Filter           | N/A |
| Hydraulic Hammer Lines              | Yes |
| Grapple and Shear Hydraulic Lines   | N/A |
| Diesel Exhaust Fluid System AddBlue | N/A |
| Stabilizer Blade Condition          | N/A |
| Horn                                | Ok  |
| Radio                               | Yes |
| Rear Camera                         | Yes |
| Operation Cataloge                  | Yes |

---

### Operator Cabin Details

|                                   |              |
|-----------------------------------|--------------|
| Seat and Arm Support              | Ok           |
| Cab Doors & covers                | Ok           |
| Control Levers, Control Stick     | Ok           |
| Windows and Mirrors               | Ok           |
| Dashboard Screen, Gauges          | Ok           |
| Warning alarms message            | Ok, AC error |
| Washer, Wipers                    | Ok           |
| Air Conditioning & Heating System | Not cooling  |
| Cab Floor Covering                | Ok           |
| Cab Structure, Guard              | Ok, no guard |
| Electrical System                 | Ok           |

---

### Engine & Performance

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |            |
|--------------------------|------------|
| Fuel Injection System    | Electronic |
| Engine Model             | C7.1       |
| Engine Cooling System    | Ok         |
| Engine Oil Check         | Ok         |
| Cooling System           | Ok         |
| Coolant                  | Ok         |
| Exhaust System & Muffler | Ok         |
| Belts & Air/Oil Filters  | Ok         |
| Smoke Check              | Normal     |
| Blowby                   | Normal     |
| Leaks & Seals            | Ok         |

---

## Exterior Condition & Visual Inspection

|                             |                                                           |
|-----------------------------|-----------------------------------------------------------|
| Main Frame & Track Frame    | Ok                                                        |
| Protective Covers & Sheets  | Ok, the cover underneath the main valve cover is missing. |
| Engine Hood                 | Ok                                                        |
| Side Access Doors           | Ok                                                        |
| Steps and Handrails         | Ok                                                        |
| Boom Condition              | Ok                                                        |
| Bumpers & Catwalk Condition | Ok                                                        |
| Arm Condition               | Ok                                                        |
| Lights                      | Ok                                                        |
| Battery Check               | Ok                                                        |
| Cabin Compartments          | Ok                                                        |
| Exterior Paint Condition    | Ok                                                        |

---

## Hydraulic System

|                              |            |
|------------------------------|------------|
| Hydraulic Leaks              | Ok         |
| Boom Hydraulic Jack          | Ok         |
| Hydraulic Pump & Valve Block | Functional |
| Bucket Hydraulic Jack        | Ok         |
| Arm Hydraulic Jack           | Ok         |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Performance analysis

|                                     |            |
|-------------------------------------|------------|
| Boom Pins Condition                 | Ok         |
| Excavator self- Drift Test          | Functional |
| Arm Pins Condition                  | Ok         |
| Hydraulic Pump Noise Check          | Minor      |
| Bucket Pins Condition               | Ok         |
| Slewing Ring Bearing Movement Check | Ok         |
| Swing Drive and Brake Test          | Ok         |
| Drive force Test                    | Ok         |

## Attachments

|                          |                                              |
|--------------------------|----------------------------------------------|
| Attachments model        | Bucket                                       |
| Size                     | W1070, H1070, D850 mm (1.19 m <sup>3</sup> ) |
| Status                   | Ok                                           |
| Coupler status           | Ok                                           |
| Second Attachments model | N/A                                          |
| Size                     | N/A                                          |
| Status                   | N/A                                          |

## Undercarriage

|                    |     |
|--------------------|-----|
| bushings           | 80% |
| Track shoes        | 80% |
| idlers             | 80% |
| shoe width in mm:  | 600 |
| track pitch in mm: | 70  |
| carrier rollers    | 80% |
| Track rollers      | 80% |
| Track links        | 80% |
| Sprocket segments  | 70% |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

